## DryFast® & DryFast Ultra® Diaphragm Vacuum Pumps

- One head service kit includes 1 diaphragm, valves and o-rings
- Two head service kit includes 2 diaphragms, valves and o-rings



Pump Model	No. Heads on Pump	KIT No.	Description
2014	1	2047K-01	One Head Service Kit
2032, 2042, 2047	2	2047K-01	One Head Service Kit
2032, 2042, 2047	2	2047K-02	Two Head Service Kit
2034, 2037, 2044	2	2037K-01	One Head Service Kit
2034, 2037, 2044	2	2037K-02	Two Head Service Kit
Tool Kit for Pump Models		KIT No.	Description
2014, 2032, 2034, 2037, 2042, 2044, 2047		826801-16	Wrench for diaphragm removal

## Self Cleaning Dry Vacuum System

- One head service kit includes 1 diaphragm, valves and o-rings
- Two head service kit includes 2 diaphragms, valves and o-rings



Pump Model	No. Heads on Pump	KIT No.	Description
2025	2	2037K-01	One head service kit
2025	2	2037K-02	Two head service Kit
2026, 2027, 2028	2	2047K-01	One head service kit
2026, 2027, 2028	2	2047K-02	Two head service kit
Tool Kit for Pump Models		KIT No.	Description
2025, 2026, 2027, 2028		826801-16	Wrench for diaphragm removal

High Flow Diaphragm Vacuum Pumps



• Service kit includes diaphrams, valves and o-rings.

Pump Model	KIT No.	Description
2054, 2052	402042-US	Four head service kit
2064, 2067, 2062, 2163	402043-US	Eight head service kit
Tool Kits for Pump Models	KIT No.	Description
2054, 2052, 2064, 2067, 2062	402106-US	Includes 19 mm wrench, Allen key and adjustable spanner wrench
2054, 2052, 2064, 2067, 2062	826801	Adjustable spanner wrench for diaphragm washer removal

## Standard Duty Dry Piston Pump Kits

• Two head service kit includes 2 connecting rod assemblies, 2 valve plate assemblies, piston cups, muffler, gaskets and o-rings



Pump Model	KIT No.	Description
Fullip Model	KII NO.	Description
2580, 2585	2585K-03	Two Head Service Kit, 2585
	2585K-04	Seal Service Kit, 2585
2562, 2567	2567K-03	Two Head Service Kit, 2562/67
	2567K-04	Seal Service Kit, 2562/67
2561	2561K-03	Two Head Service Kit, 2561
Note!: Models older than and including Dec. 2007, date code 1207xxxx.	2561K-04	Seal Service Kit, 2561
2561	2563K-03	Two Head Service Kit, 2567
Note <sup>2</sup> : Models newer than and including Jan 2008, date code 0108xxxx.		(Includes Seal Service Kit)
2563	2563K-03	Two Head Service Kit, 2563
2581	2581K-03	Two Head Service Kit, 2581
	2581K-04	Seal Service Kit, 2581
All Models WOB-L* Dry Pump	2500K-04	Service Kit for Feet